

Architect

Ron Ward Webb

1659 W. Hanrahan Road
Ayden, NC, 28513
Tel: (252) 606-7860
Email: Wgarryowen@cs.com

To: Mr. Tommy McLeod, STE Contractors
From: Ron Ward Webb, Architect, NCARB
Date: Monday, April 28, 2025
Re: Grease Interceptor Substitute Request
Mount Pisgah Harnett OFWB Church MAC Addition

Mr. McLeod

I have checked with the Project Engineer on the proposed Substitute and he has informed that, while the flow rate is equal, the capacity for solid waste storage is less than the originally specified grease interceptor. It is my understanding that, due to the Kitchen being a warming kitchen, the Health Department decision does not enter into this issue. Also, based on your email received this date, I am informed that the Church is aware of having to clean more often due to less capacity for storage, and that this is approved by them.

Based on the above facts, the proposed grease interceptor substitute can be approved. Please do not hesitate to call me if I need to make further clarifications on this issue. Thank you.

Sincerely

Ron Ward Webb, Architect, NCARB

cc: R. Hinton, file
code: GI Sub

