HARNETT REGIONAL WATER BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

Electronically send to utilitybilling@harnett.org

	4960417						
Service A		hn Fugury Va	eriacy NC 27	526)		
Meter #: Company	:08-01-2025 90266769 :Drain Magic = Forigation	Zne					
	Reduced Pre	oly	RP ☑ DCDA□ DC □ RPDA□				
	Double Check Valve A	Assembly			PVB □ SVB □	Air G	ap□ ′B□
ŗ .	Check Valve #1	Check Valve #2	Relief Valve		PVB/SVB		
Initial Test	Leaked Closed Tight	Leaked Closed Tight	Did not Open		AIR INLET Did not Open		
	Held at 7.3 PSID	Held at 1.6 PSID	Opened at <u>3.7</u> P	PSID	Opened at		SID
Repairs Details	Cleaned	Cleaned	Cleaned		CHECK VA Leaked Held at		PSID
					Cleaned Replaced AIR INLET Opened at		PSID
Final	Closed Tight	Closed Tight			CHECK VA	ALVE	
Test	Held atPSID	Held atPSID	Opened at	PSID	Held at		PSID
Commen					Line Pressure Meter Reading d Backpressure #2 Shutof	<u>ממוזי</u> 7. f 7.	12.81 3
					ief Valve Exercised 4.6		
Initial Test	Date/Time Tester 08/01/2024 9:574m Bo	Signature Bythent Bolly L	Tester # C-411		Test Kit TkbL 60165 - 08-24	Passed	Failed
Repairs				05	- 08- 2 4		
Final Test							
	PO Box 1119 Lillington, NC 27546					(910)8 (910) 8	