

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** _____ ✓

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Manufactured
Name: McLoey Kenneth Paul

Address: 533 Samuel McLoey

Date: 2/5/18

Building Official: [Signature]

Permit Numbers

Building: _____
Electrical: _____
Insulation: _____
Plumbing: _____
Mechanical: _____
MFG Home: _____

500 ✓ 1738

ADDRESS : 533 SAMUEL MCKOY LN SUBDIV: MORGAN PARTITION
 CONTRACTOR : PHONE :
 OWNER : MCKOY KENNETH RAY PHONE :
 PARCEL : 10-0549-12-01-0321- - -
 APPL NUMBER: 17-50041738 CP MANUFACTURED HOME RA20R/RA20M CRITERIA
 DIRECTIONS : T/S: 06/30/2017 10:05 AM JBRÖCK ----
 HWY 27 W TO SPRINGWOOD LANE TO SAMUEL
 MCKOY LANE 1ST HOUSE ON LEFT ABOUT 7
 TENTHS OF A MILE DOWN DIRT ROAD

STRUCTURE: 000 000 32X76 4BDR DWMH W/ FUTURE F/B PORCH/DECK

FLOOD ZONE : FLOOD ZONE X
 # BATHS : 2 # BEDROOMS : 4000000.00
 MOBILE HOME YEAR : 2017000.00 PROPOSED USE : DWMH
 SEPTIC - EXISTING? : NEW TANK WATER SUPPLY : EXISTING WELL

PERMIT: CPDW 00 CP MOBILE HOME DOUBLEWIDE

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	12/22/17 12/28/17	AC AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 003071701 T/S: 12/28/2017 01:13 PM SSTEWARD T/S: 12/28/2017 01:14 PM SSTEWARD
T501 01	1/08/18 1/08/18	TSG DA	R*MOBILE HOME FOUND./ M. WALL VRU #: 003073160 T/S: 01/08/2018 03:00 PM BPETRICH DRAIN TEST FROZEN AND NEED MARRIAGE WALL ATTACHMENT PAPERWORK TO VERIFY CORRECT INSTALL.
T501 02	1/10/18 1/10/18	TSG AP	R*MOBILE HOME FOUND./ M. WALL VRU #: 003074259 second marrige wall inspection required for sheathing nail pattern
T501 03	1/11/18 1/11/18	TSG AP	R*MOBILE HOME FOUND./ M. WALL TIME: 17:00 VRU #: 003074713 * OVERRIDE TAKEN BY LLUCAS DATE: 01/10/18 TIME: 10:13:22 T/S: 01/10/2018 10:13 AM LLUCAS PER SCOTT PUT BACK ON TO LOOK AT OSB ON OUTSIDE MARRIAGE WALL - PM REQUEST *** INFORMED CONTRACTOR REPS ON SITE AND HOME OWNER THAT CURTIN WALL AT 40"AND HIGHER REQUIRE AN INSPECTION FOR THE FOOTING
A814 02	1/16/18 1/16/18	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003076908 533 SAMUEL MCKOY LN LILLINGTON 27546 T/S: 01/16/2018 12:27 PM SBENNETT
T501 04	1/16/18 1/16/18	TSG AP	R*MOBILE HOME FOUND./ M. WALL TIME: 17:00 VRU #: 003075710 T/S: 01/11/2018 03:01 PM LLUCAS T/S: 01/11/2018 03:02 PM LLUCAS
Z818 01	1/25/18 1/25/18	AD AP	PZ*ZONING INSPECTION VRU #: 003079878 T/S: 01/25/2018 10:52 AM ADRIGGER
T507 01	1/31/18 1/30/18	BP CA	R*MANUFACTURED HOME FINAL VRU #: 003082765 T/S: 01/30/2018 03:38 PM BPETRICH CANCELLED - CANNOT HAVE FINAL BEFORE WELL HAS BEEN FINALED. NO NUMBER LEFT WHEN INSPECTION WAS SCHEDULED THROUGH AUTOMATED SYSTEM, CALLED SAMUEL MCKOY AT 910.658.6668 AND LEFT MESSAGE EXPLAINING @ 3:40P 1/30
T507 02	2/01/18 2/01/18	MC DA	R*MANUFACTURED HOME FINAL TIME: 17:00 VRU #: 003083516 T/S: 01/31/2018 09:26 AM LLUCAS PER ANDREW CURRIN CUSTOMER IS USING HIS OLD WELL AND THAT IS OK.

PREPARED 2/02/18, 14:35:25
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 14
DATE 2/05/18

ADDRESS : 533 SAMUEL MCKOY LN
CONTRACTOR :
OWNER : MCKOY KENNETH RAY
PARCEL : 10-0549-12-01-0321- - -
APPL NUMBER: 17-50041738 CP MANUFACTURED HOME RA20R/RA20M CRITERIA

SUBDIV: MORGAN PARTITION
PHONE :
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			T/S: 02/01/2018 03:21 PM MCOOK ----- 1. WRONG ADDRESS POSTED 2. FRONT AND BACK STEPS NEED RISER BOARDS INSTALLED MAX. 4 INCH GAP IN RISER 3. PROPRLY LEVEL STEPS FRONT AND BACK 4. REMOVE DEBRIS FROM UNDER HOUSE 5. PROVIDE PROPER GRADE AT FRONT AND RIGHT SIDE 6" FALL WITHIN 10'
T507 03	2/05/18	TI	R*MANUFACTURED HOME FINAL VRU #: 003084886

COMMENTS AND NOTES