(NOT TO SCALE) TOWN OF DEED REFERENCE: COATS LEGEND: LINE LEGEND: Deed Book 1081, Page 241 FIP Found Iron Pipe NOTES: Plat Cabinet F, Slide 348C Subject Tract Surveyed Set Iron Pipe FCM.. .Found Concrete Monument Subject Tract Not Surveyed This property does not appear to be located Found P.K. Nail FPK. within 2000 feet of N. C. Grid Monumentation. PKS.. .Set P.K. Nail ZONED: RA-30 FRB. .Found Rebar Lot Lines MINIMUM SETBACK REQUIREMENT All measurements shown are horizontal ground SRB. .Set Rebar measurements unless otherwise noted. R/W. .Right of Way Easement Line SR 1559 Front ----35' . Centerline Side----10' CP ..Computed Point Area calculated by computer. Road Centerline Rear----25' FRRS. Found Railroad Spike SR 1560 Set #4 rebar at all corners unless otherwise indicated. SRRS.. Set Railroad Spike Surveyed Lines, R/W or Tie Line AXF... .Found Axle Adjoining References are From the County GIS Office Found Lightwood Knot FLK.. Not to Scale SR 1561 and other sources and May Not Have Been Verified BOBBY POPE by this Office. Deed Book 653, Page 330 "\*" Denotes Control Corner. S 85°20'17" F State of North Carolina County of Harnett **BRANCH** I,\_\_\_\_\_, Review Officer of Harnett County, certify that the map or plat to which this certification is affixed meets all statuatory requirements for recording. BOBBY POPE Deed Book 653, Page 330 Date Review Officer 1.81 Acres TOTAL 0.24 Acres in R/W BOBBY POPE 1.57 Acres NET Deed Book 653, Page 330 NORTH CAROLINA HARNETT COUNTY This Map/ Plat was presented for registration and recorded FRB in this office at Map Number \_\_\_\_\_\_ This \_\_\_\_\_ day of \_\_\_\_\_at \_\_\_\_o'clock \_\_\_ M. KIMBERLY S. HARGROVE Register of Deeds FRB Asst./Deputy Register of Deeds Mobile Hom 60' R/W EBENEZER CHURCH ROAD SR 1558 s 79°35'40" W FPK CL SR 1558 & CL SR 1554 **EXISTING PARCEL** SURVEY FOR: FRED ALLEN

NORTH CAROLINA HARNETT COUNTY

I, J. Scott Walker, a Professional Land Surveyor, certify that this plat was drawn under my supervision from an actual survey made under my supervision (deed description recorded per deed references as stated on map), that the ratio of precision as calculated by lattitude and departures is 1/10000+, that the boundaries not surveyed are shown as broken lines plotted from information as shown on map, that this plat was prepared in accordance with G.S. 47-30 as amended. Witness my original signature, registration number, and seal this 10th day of July, A.D., 2018.

Surveyor L-4332

Not For Sales, Conveyances, or Recordation

NOTE: Boundary was Surveyed December 5, 2017. Mapping and Location for New Mobile Home was by this Office. Smaller or Buildings in Poor Repair May Not be Shown.

JULY 8, 2018

HARNETT CO.,

J. SCOTT WALKER

Phone: (910) 897-5753


835 Abbatoir Road, Coats, NC 27521

GROVE TWP.,

SURVEY BY:

VICINITY MAP

GRAPHIC SCALE



PID - 071600 0212 01 PIN - 1601-80-9520.000

Registration Number