

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363

Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

September 10,2018

Raymor Builders

Phone: 919-427-7521 ; e-mailed to: raynorbuilders.es@gmail.com ;

araynorapw@embarqmail.com

Engineering - Foundation Analysis

12 Trace Turner Lane; Coats , NC


Project No.:18DDM-0910F

To Whom It May Concern/Inspections Dept.:

The undersigned arrived on-site 9-10-18 to observe and test the in-place conditions for the above referenced site. Based on the testing (Per ATM Special publication 399) the bearing materials (Tan to tan silty sandy clay soils with gravel (Unified Soil Classification System - CL/ML)) were adequate to support the planned structure.

Sincerely,

David Miller, PE



9/11/2018 1:33:39 AM PDT

DEM/18DDM-0910F