

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612
(919) 422-8932 (Office); DAVE@DMA-PA.COM

May 13, 2019

Weaver Development Company
DBA: Weaver Homes
309 Wagoner Drive
Fayetteville, NC 28303
Duston Blackwell 919-606-4696
e-mailed to: edb1971@gmail.com

RE: Engineering - Foundation Testing
161 Peacock Road ; Sanford, NC
Project No.:19DDM-0513G

To whom it may concern:


The undersigned arrived on-site previously and on 5-13-19 to observe, probe and perform Dynamic Cone Penetrometer (DCP) testing in general accordance with the American Standard Testing Methods (ASTM) special publication 399 on the exposed foundation and slab sub grade fill soils at the above referenced site. Based on the observations the tannish clayey sandy fill soils were adequately compacted to 95% of the Standard Proctor Maximum Dry Density from the testing outlined above.

Sincerely,

David Miller, PE

DEM/19DDM-0513G

DocuSigned by:



AED026D4715F4DC...



5/13/2019