

**Howerton Services, PLLC**  
**License # P-1716**  
3513 Cathedral Bell Road  
Raleigh, NC 27614  
(919) 270-3460

June 14, 2019

Subject: 3411 Oakridge River Road  
Fuquay Varina, NC 27526  
Harnett County Permit #: SFD1903-0021  
Framing Inspection Letter

Based on the request of the inspector, I looked at 2 items for compliance. My assessment and recommendations are as follows:

- Item 1 – Using bolts on the 7" x 9 1/4" LVL is acceptable. However, the current bolt pattern is not sufficient to properly fasten the 4 members together. I would recommend adding 2 rows of Simpson SDWS 0.220" x 6" structural screws spaced at 16" centers. The rows should be 2" from the top and bottom of the beam.
- Item 2 – Place a double 2x4 stud column under each ridge beam supporting valley rafters. Place double ceiling joists under each stud column.



*Joel S. Howerton*

06 14 2019

# Signature Certificate

Folder Ref: 5edad4d4775fa4e5ec9204d537c1baf5e26907e6



Author: Joel S. Howerton      Creation Date: 14 Jun 2019, 18:13:00, EDT      Completion Date: 14 Jun 2019, 18:14:06, EDT

## Document Details:



Name: Jones Residence Framing Inspection Letter

Type:

Document Ref: d885b9101d3dc886c1ce42b6ebf6c8d4e7b7131af7a48eb799fe  
abbe535aafe0

Document      1  
Total Pages:

## Document Signed By:

Name: Joel S. Howerton  
Email: joeltarheel66@yahoo.com  
IP: 2606:a000:1128:c4cb:fc49:8e4f:7045:7fec  
Date: 14 Jun 2019, 18:14:06, EDT

## Document History:

Folder Created      Joel S. Howerton created this folder on 14 Jun 2019, 18:13:00, EDT  
Invitation Sent      Invitation sent to Joel S. Howerton on 14 Jun 2019, 18:13:49, EDT  
Invitation Accepted      Invitation accepted by Joel S. Howerton on 14 Jun 2019, 18:13:49, EDT  
Signed By Joel S. Howerton      Joel S. Howerton signed this folder on 14 Jun 2019, 18:14:06, EDT  
Executed      Document(s) successfully executed on 14 Jun 2019, 18:14:06, EDT

