



System: --Repair:

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
 *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



System: Pressure Manifold Lines: 8-12, (420') Accepted Status System 0.35 Soil LTAR 18" Trench Bottom

Repair: T&J Panel Lines: 1-8, (280') Accepted Status System 0.35 Soil LTAR 18" Trench Bottom



Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4—Bedroom Septic Layout Lot 4, Masons Pointe Subdivision Harnett County, North Carolina

Job# : 2031 Drawn By : AH & TMB Date: 04/22/2019 Revision: 10/23/2019