

System: ---Repair: ——

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



System: Gravity to Serial Dist. Lines: 2-4, (375') Accepted Status System

0.35 Soil LTAR 24" Trench Bottom

Repair: Gravity to Serial Dist.

Lines: 5-8, (295') Accepted Status System

0.35 Soil LTAR

T&J Panel 50% Reduction



Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4—Bedroom Septic Layout Lot 12, Masons Pointe Subdivision Harnett County, North Carolina Job# : 2031 Drawn By : AH Date : 11/12/2019 Revision: