



I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this 7TH day of FEBRUARY 2020.



BK 2013 PG 5
HARNETT CO. REGISTRY



SETBACKS


FRONT	25'
REAR	20'
SIDE	10'
CORNER SIDE	20'

C1 R=340.00' L=70.24' S89°05'55"W 70.12'

THIS PROPERTY IS NOT LOCATED
IN THE 100 YEAR FLOOD ZONE.

LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IPS	IRON PIPE SET	WM	WATER METER
R/W	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



GRIFFIN LAND SURVEYING, INC.

P. O. BOX 148
FUQUAY-VARINA, NC 27526
(919) - 567-1963

FOUNDATION SURVEY

FOR

H & H HOMES

WOODSHIRE

LOT 403

WOOD POINT DRIVE

NORTH CAROLINA

HARNETT CO. ANDERSON CREEK TWSHP

DRAWN BY **KDF**

DATE **2/7/20**

CHECKED BY **MPG**

SCALE **1" = 40'**