



Permit Inspections

Harnett County

Permit Number: SFD2001-0006

Description: **85x64 sfd, 3 bedrooms 4 baths**

Applied: **1/3/2020**

Approved: **4/14/2020**

Site Address: **168 SHERWOOD LN**

Issued: **7/7/2020**

Finalized:

City, State Zip Code: **SANFORD, NC 27332**

Status: **ISSUED**

Applicant: **South Eastern General Contracting, Inc.**

Parent Permit:

Owner: **FURNE CHAD W**

Parent Project:

Contractor: **South Eastern General Contracting, Inc.**

Details:

LIST OF INSPECTIONS

SEQ ID	SCHEDULED DATE	COMPLETED DATE	TYPE	INSPECTOR	RESULT	REMARKS
			FOUNDATION SURVEY	CP Bucket		NOT NEEDED
Notes:						
			SLAB SFD STEMWALL	Slade Burton Lawson III		
Notes:						
			TEMP POWER CERTIFICATION	Slade Burton Lawson III		
Notes:						
	7/14/2020	7/14/2020	FOOTING SFD STEMWALL	Slade Burton Lawson III	DISAPPROVED	
Notes: Need compaction test performed left side front and rear corners						
	7/16/2020	7/16/2020	FOOTING SFD STEMWALL	Slade Burton Lawson III	APPROVED	
Notes:						
	7/16/2020	7/16/2020	T-POLE	Slade Burton Lawson III	APPROVED	
Notes:						
	8/14/2020	8/14/2020	WATER CONNECTION	Steven Gazlay	DISAPPROVED	lock box code is 9525
Notes: lock box code is 9525 Inspector SBL changed the inspection assignment from SBL to SPG Ok to set meter for temp water. Waterline not installed to house. Ok to set meter for temp water. Waterline not installed to house.						





Permit Inspections Harnett County

	8/19/2020	8/19/2020	UNDER SLAB TRADES	Slade Burton Lawson III	APPROVED	
Notes: USE PLAN IN ATTACHMENTS						
	8/26/2020	8/26/2020	FOUNDATION SFD STEMWALL	Slade Burton Lawson III	DISAPPROVED	
Notes: CUS REQUEST AM Need compaction test done on backfill .						
	8/31/2020	9/2/2020	FOUNDATION SFD STEMWALL	Slade Burton Lawson III	APPROVED	
Notes:						
	10/30/2020	10/30/2020	ROUGH IN	Slade Burton Lawson III	DISAPPROVED	
Notes: 2x2 sq washers wing walls, anchors center 1/3 throughout, anchors both sides plate breaks within 12", fasten 2 ply lvl one side, fasten 3 ply lvl both sides, air barrier under stairs, flow fill around plumbing lines, 3 full length studs header 6'-9', 4 full length studs headers 9'-12', missing insulation baffles, fire caulk plumbing 2nd floor bath, engineer letter on up set headers, strap 4 or more stud columns, head test down, pack out open web pantry for complete nail pattern hanger, mech fasten interior load bearing walls. Do not insulate.						
	11/5/2020	11/5/2020	ROUGH IN	Slade Burton Lawson III	CANCELLED	
Notes:						
	11/16/2020	11/16/2020	ROUGH IN	Slade Burton Lawson III	FAIL W/ PENALTY	
Notes: Head test down, missing anchors garage wing walls, tight all anchors						
	11/16/2020	11/16/2020	INSULATION	Slade Burton Lawson III	DISAPPROVED	
Notes: Must pass rough in first						
	11/18/2020	11/18/2020	ROUGH IN	Slade Burton Lawson III	APPROVED	
Notes:						
	11/18/2020	11/18/2020	INSULATION	Slade Burton Lawson III	APPROVED	
Notes:						
	11/19/2020	11/19/2020	ADDRESS	GIS Bucket	APPROVED	
Notes: 168 SHERWOOD LN SANFORD 27332.						
	6/15/2021	6/15/2021	WATER CONNECTION	Slade Burton Lawson III	FAIL W/ PENALTY	lock box code is 9525
Notes: Line covered						





Permit Inspections Harnett County

	6/15/2021	6/15/2021	SEWER CONNECTION	Slade Burton Lawson III	DISAPPROVED	
Notes: Line covered						
	6/21/2021	6/21/2021	WATER CONNECTION	Slade Burton Lawson III	DISAPPROVED	lock box code is 9525
Notes: Seal around sleeve at foundation, ok to cover with exception of 2' out from foundation						
	6/21/2021	6/21/2021	SEWER CONNECTION	Slade Burton Lawson III	APPROVED	
Notes:						
	6/24/2021	6/24/2021	WATER CONNECTION	Steven Gazlay	FAIL W/ PENALTY	lock box code is 9525
Notes: Inspector SBL changed the inspection assignment from SBL to SPG Address items from previous inspection.						
	6/30/2021	6/30/2021	WATER CONNECTION	Slade Burton Lawson III	APPROVED	lock box code is 9525or 1003
Notes: Kennedy will call Wed am to see what time so plumber can be on site						
	7/20/2021	7/20/2021	TEMP POWER CERTIFICATION	Steven Gazlay	FAIL W/ PENALTY	
Notes: Inspector SBL changed the inspection assignment from SBL to SPG Provide correct lockbox code.						
	7/21/2021	7/21/2021	TEMP POWER CERTIFICATION	Slade Burton Lawson III	DISAPPROVED	
Notes: lock box code 1995 Faceplates missing throughout, exposed wires exterior left side rear exit door, access to air handlers not provided						
50			FINAL SFD MONO**	Slade Burton Lawson III		
Notes:						