

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

11/17/2020

SUBJECT: **SFD2001-0057**

SINGLE FAMILY DWELLING

To: SOUTH SCAN INC

Here are the results of all Inspections located at 825 COACHMAN WAY:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: Completed Date/Time:

Inspector: CP Bucket

Result: Remarks: Notes:

Inspection Type: T-POLE

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 5/27/2020
Completed Date/Time: 5/27/2020

Inspector: Slade Burton Lawson III

Result: DISAPPROVED

Remarks:

Notes:

From 15' off of front left corner provide compaction test on footings past that point



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOOTING
Scheduled Date/Time: 6/1/2020
Completed Date/Time: 6/1/2020
Inspector: Scott Guy
Result: APPROVED

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to TSG

Inspection Type: FOUNDATION
Scheduled Date/Time: 6/25/2020
Completed Date/Time: 6/25/2020
Inspector: Steven Gazlay
Result: APPROVED

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG

Engineering letter required if unbalanced backfill will exceed four feet. Compaction letter

required for porch fills greater than 24"

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 7/1/2020
Completed Date/Time: 7/1/2020
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG

Provide paperwork an tgi layout and information.

Inspection Type: OPEN FLOOR Scheduled Date/Time: 7/6/2020 Completed Date/Time: 7/6/2020

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 8/18/2020
Completed Date/Time: 8/18/2020
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type:

Porch already poured Compaction test required for fills over 2 feet. No plans on-site. Missing Scheduled Date/Time: truss wind bracing. Insulate water line in garage. Missing porch post and attachments. Provide Completed Date/Time: engineering letter on upset headers. Provide draft stopping under stairs at knee wall. Add king

Inspector:

studs to dividing garage wall header.

Dacul+

Inspection Type: **ROUGH IN** Scheduled Date/Time: 8/25/2020 Completed Date/Time: 8/25/2020

Slade Burton Lawson III Inspector:

APPROVED Result:

Remarks: Notes:

Inspection Type: **INSULATION** Scheduled Date/Time: 8/27/2020 Completed Date/Time: 8/27/2020 Inspector: Steven Gazlay **APPROVED** Result:

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG

ADDRESS Inspection Type: Scheduled Date/Time: 10/6/2020 Completed Date/Time: 10/6/2020 **GIS Bucket** Inspector: Result: **APPROVED**

Remarks:

Notes:

825 COACHMAN WAY SANFORD 27332.

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 10/7/2020 Completed Date/Time: 10/7/2020 Inspector: Steven Gazlay Result: **APPROVED**

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG

Inspection Type: **SEWER CONNECTION**

Scheduled Date/Time: 10/7/2020 Completed Date/Time: 10/7/2020 Inspector: Steven Gazlay Result: **APPROVED**

Remarks:

Notes: Inspector SBL changed the inspection assignment from SBL to SPG



108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 11/13/2020 Completed Date/Time: 11/13/2020

Inspector: Slade Burton Lawson III

Result: DISAPPROVED

Remarks:

Notes:

Missing face plate master vanity receptacle, 1926.1053(b)(1)When portable ladders are used for access to an upper landing surface, the ladder side rails shall extend at least 3 feet (.9 m) above the upper landing surface to which the ladder is used to gain access; or, when such an extension is not possible because of the ladder's length, then the ladder shall be secured at its top to a rigid support that will not deflect, and a grasping device, such as a grabrail, shall be provided to assist employees in mounting and dismounting the ladder. In no case shall the extension be such that ladder deflection under a load would, by itself, cause the ladder to slip off its support.

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 11/16/2020 Completed Date/Time: 11/16/2020

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: Notes: