

т 919 773-1200 = F 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com

June 4, 2020

C & C Services Chad Tyndall 3782 Tyndall Bridge Road Salemburg, NC 28385

Fax: 910-564-6633

Reference: Engineering Services

60 Starlight Drive Lillington, NC

Project No.: 2001-020357

To Whom It May Concern:

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) has reviewed analyzed the following project items:

1) Address the in-situ bearing conditions of the existing footing excavation prior to concrete placement.

The following conclusions and recommendations were noted:

1) Based on our conversations with the contractor and supplemental analyses, it TE&D's understanding that the existing footing excavations had areas of shallow standing water at the time of the previous municipality inspection on the morning of June 3, 2020. The standing water and loose material had been adequately removed at the time of TE&D's June 3, 2020 afternoon analyses of the footing excavations. The existing bearing conditions were deemed adequate to support the anticipated loading conditions (i.e. 2000 psf net design bearing pressure). The reader is referred to the attached photographs for supplemental information.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us. Sincerely,

Tyndall Engineering & Design

Prentice A. Tyndall Jr., PE

PTII | 2001-20357





т 919 773-1200 = F 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com







τ 919 773-1200 = ε 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com



