

# Wayne R. Dashfield, PE

421-B South Bright Leaf Blvd. Smithfield, NC 27577

(919) 934-0961

June 29, 2020

Re: Footing outside Middle Third  
305 Southern Place  
Lillington, NC

To: Harnett County Inspections

On June 24, 2020 I made an onsite visit to 305 Southern Place located in Lillington, North Carolina. The purpose of this visit was to inspect the pier foundation footings in which the resultants were outside the middle third of the footing.

It is a good practice, in general to have the resultant located within the middle third. However in a foundation on a very incompressible soil or a low loading such as in this case, the resultant can be allowed to fall outside the middle third.

I will certify that the resultant loading will not induce over turning or excessive settlement on sections of the footing. If I can be of any more assistance, please feel free to contact me.

Yours truly,

Wayne R. Dashfield, PE

