## Enoch ngineers, P.A.

Joe E. Godwin Sr., P.E., P.L.S.

**Consulting Engineers & Surveyors** 

Phone: (919) 894-5731 (919) 894-7765

Fax: (919) 894-8190

Fleet Temple, P.E.

Jason E. Godwin, P.L.S.

1403 NC Highway 50 South Benson, North Carolina 27504

Email: general@enochengineers.com

August 5, 2020

KC Concrete 203 A Mingo Rd. Benson, NC 27504

Attention: Brandon Moore

RE: Structural

Subject:

834 Mamie Upchurch Road

Lillington North Carolina 27546

To Whom It May Concern:

Our office has performed a structural evaluation of the CMU foundation wall repair at subject referenced above on August  $4^{th}$ , 2020. The CMU foundation wall on the left side of the house envelope was found to be structurally stable and shows no signs of failure. No repair recommendations are issued at this time of inspection. Backfill the interior soil to the 95% or greater compaction standard.

No follow up inspection is required.

If we may be of further assistance, please feel free to call.

Respectfully,

Joe E Godwin Sr., P.E. Enoch Engineers, P.A.

JEG Sr. / BH