

MARSHALL ENGINEERING SERVICES, PLLC

7575 McArtans Ford

Linden, NC 28356

(910) 850 5874

Corp. License P-0682

[Randolph@RandolphMarshall.com](mailto:Randolph@RandolphMarshall.com)

Craig Byrd

December 5, 2020

Subject: 120 Will Lucas Road  
Linden, NC 28356


I visited your home construction site at the above address to assess a comment made by a government building inspector regarding window and door headers.

The 2"x10" headers are installed under the top sill plates, which is an unusual construction technique but is adequate for this building. The window and door headers are correctly sized and have the necessary support studs. The imposed loads are transferred through the studs to the foundation below as required.

These headers are structurally sound and do not impact the structural integrity of the remaining framing.

Please call my office if you have any questions or need additional engineering support.

Sincerely,



E. Randolph Marshall, PE

