

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

September 14,2020

Southern Touch Homes, LLC
PO Box 2135
Angier, NC 27501

Bryant Lockamy Phone: 919-524-3354 e-mailed to: southerntouchhomesllc@gmail.com


Re: Engineering - Foundation
679 Rawls Club Road; FuQuay Varina, Harnett County, NC
Project No.:20DDM-0914C

To Whom It May Concern:

The undersigned arrived on-site on 9-14-20 to observe and probe the exposed foundation bearing conditions for the planned structure. Based on the observations and probing the exposed bearing materials (reddish tan sandy clays) were over excavated approximately 2 to 3 feet to firm bearing conditions along the left portion of the structure. The over excavated area can be filled with concrete during the concrete placement or filled with clean washed stone to the planned footing bearing level prior to concrete placement to provide the required bearing capacity per the 2018 Residential North Carolina State Building Code (NCSBC) of 2000 PSF.

Sincerely,

David Miller, PE



DEM/20DDM-0914C