Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

SF02011-0001

	SOUTH CREEK
	LOT SO
Property Size:	20
_	_
Spring	Other
☐ Mixed	

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
112,3	L3-4%	0-12	Coz LS	W 5 1					PS
		12-48	on ser	W 51		46			0.375
						12			

Description	Initial	Repair System	Other Factors (.1946):		
_	System		Site Classification (.1948):	PRENISIGNALLY SNITABLE	
Available Space (.1945)	1/		Evaluated By:		
System Type(s)	252 43	252 MES	Others Present:	ANDREW COMIN	
Site LTAR	0.375	C.375			

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
	IV	SIC-SILTY CLAY	0.4 - 0.1		

ΙV SIC-SILTY CLAY C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

STRUCTURE

GR-GRANULAR SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY Show profile locations and other site features (dimensions, references or penchmark, and North) PR-PRISMATIC N N 5 ä 也 PIN ATTENDO

THUNDER VALLET CT.