


I, MICHAEL P. GRIFFIN, certify that under my direction and supervision this map was drawn from an actual field survey; that the error of closure of the map as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates.

Witness my hand and seal this day of MONTH 2020.

JONATHAN & KATHERINE GRIFFIN
 PIN #064-65-1818.000
 D.B. 1137 PG. 456

BK 2019 PGS 421-424
 HANNETT CO. REGISTRY



NEW IMPERVIOUS RECORDING
 PB 2020 PG 306

IMPERVIOUS AREAS

HOUSE	2419 SQ. FT.
DRIVE & WALKS	1045 SQ. FT.
PATIO	000 SQ. FT.
TOTAL	3464 SQ. FT.
ALLOWED	3724 SQ. FT.

SETBACKS


FRONT	35'
REAR	25'
SIDE	10'
CORNER SIDE	20'

REVISION: NEW PLANS 10/16/20

PRELIMINARY
 NOT FOR RECORDATION,
 SALES OR CONVEYANCE


LEGEND

EIP	EXISTING IRON PIPE	FES	FLARED END SECTION
IP5	IRON PIPE SET	WM	WATER METER
RW	RIGHT OF WAY	CO	CLEAN OUT
N/F	NOW OR FORMERLY	FH	FIRE HYDRANT
EIS	EXISTING IRON STAKE	CB	CATCH BASIN



PLOT PLAN

Olde Mill Village 4-Bedroom Septic Proposal Lot #42



(42)
83,214 SF
1.910 AC

System: Gravity to D-Box
 Lines: 1-3 (405')
 0.3 LTAR
 24" Trench Bottom
 Accepted Status System
 Repair: Gravity to D-Box
 Lines: 4-6 (405')
 0.3 LTAR
 18" Trench Bottom
 Accepted Status System

Mill Bend Drive
 50' Public R/W

*Preliminary Design
 Not a Permit

Adams
 Soil Consulting
 919-414-6761
 Job #699

