
Harnett County Department of Public Health

Improvement Permit

A building permit cannot be issued with only an Improvement Permit PROPERTY LOCATION: 344 Windy Farm Dr. (Christian Lt. Rd. - SR ISSUED TO: KB Homes Carolinas SUBDIVISION Highland Grove NEW X Site Improvements required prior to Construction Authorization Issuance: Type of Structure: 3-Bedroom 50x42 SFD Proposed Wastewater System Type: 25% Reduction Sys. Projected Daily Flow: 360 Number of bedrooms: 3 Number of Occupants: 6 Basement Yes ☐ No Pump Required: Yes May be required based on final location and elevations of facilities Type of Water Supply: Community Public Well Distance from well NA Permit valid for: X Five years No expiration Permit conditions: 02/17/2021 The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements. This site is subject to revocation if the site plan, plat, or the intended use changes. The Improvement Permit shall not be affected by a change in ownership of the site. This permit is subject to compliance with the provisions of the Laws and Rules for Sewage Treatment and Disposal and to conditions of this permit. Construction Authorization (Required for Building Permit) The construction and installation requirements of Rules .1950, .1952, .1954, .1955, .1956, .1957, .1958, and .1959 are incorporated by references into this permit and shall be met. Systems shall be installed in accordance with the attached system layout. ISSUED TO: KB Homes Carolinas PROPERTY LOCATION: 344 Windy Farm Dr. (Christian Lt. Rd. -SUBDIVISION Highland Grove Facility Type: 3-Bedroom 50x42 SFD Expansion X No Basement Fixtures? Yes Basement? Yes Type of Wastewater System** 25% Reduction System (Initial) Wastewater Flow: 360 (See note below, if applicable) 25% Reduction System Number of trenches 3 Installation Requirements/Conditions Feet on Center Septic Tank Size 1000 Exact length of each trench 100 Trench Spacing: 9 gallons Pump Tank Size _____ Trenches shall be installed on contour at a Soil Cover: 12 inches gallons Maximum Trench Depth of: 24 inches (Maximum soil cover shall not exceed (Trench bottoms shall be level to +/-1/4" 36" above the trench bottom) in all directions) NA ft. TDH vs. inches below pipe Pump Requirements: Aggregate Depth: NA inches above pipe Conditions: Proposal By Adams Soil Consulting inches total WATER LINES (INCLUDING IRRIGATION) MUST BE 10FT. FROM ANY PART OF SEPTIC SYSTEM OR REPAIR AREA. NO UTILITIES ALLOWED IN INITIAL OR REPAIR DRAIN FIELD AREA. **If applicable: I understand the system type specified is different from the type specified on the application. I accept the specifications of this permit. Owner/Legal Representative Signature: This Construction Authorization is subject to revocation if the site plan, plat, or the intended use changes. The Construction Authorization shall not be transferred when there is a change in ownership of the site. This SEE ATTACHED SITE SKETCH Construction Authorization is subject to compliance with the provisions of the Laws and Rules for Sewage Treatment and Disposal and to the conditions of this permit. Construction Authorization Expiration Date: 02/17/2026 ANDREW COMIN


Harnett County Department of Public Health Site Sketch

Property Location: 344 Windy Farm Dr. (Ch	ristian Lt. Rd SR 1412)		
Issued To: KB Homes Carolinas	Subdivision Highland Grove		Lot # 8
Authorized State Agent:	ANDREW CURRY	Date: _	02/17/2021



This drawing is for illustrative purposes only. System installation must meet all pertinent laws, rules, and regulations.

Highland Grove 3-Bedroom Septic Proposal Lot #8



Windy Farm Drive

(8)

25,716 SQ.FT.

*If plumbing is not sufficient a seperate pump and tank may be required.

System: Gravity to D-Box Lines: 1-3 (300') 0.3 LTAR 24" Trench Bottom Accepted Status System Repair: Gravity to D-Box Lines: 4-6 (300') 0.3 LTAR 24 Trench Bottom Accepted Status System

> Adams Soil Consulting 919-414-6761 Job #561