

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363

Raleigh, NC 27612

(919) 422-8932 (Office); DAVE@DMA-PA.COM

July 1,2021

Weaver Development Company

DBA: Weaver Homes

309 Wagoner Drive

Fayetteville, NC 28303

Johnny 910-978-0435

Brooke Weaver ; brooke@weaver-homes.com

e-mailed to: johnny@weaver-homes.com ; Duston Blackwell 919-606-4696

e-mailed to: cdb1971@gmail.com ;

RE: Engineering - Foundation Analysis

15649 McDougald Road, Sanford, NC

Project No.:21DDM-0629Er

To whom it may concern:

The undersigned arrived on-site 6-29-21 to observe, probe and perform Dynamic Cone Penetrometer (DCP) testing in general accordance with the American Standard Testing Methods (ASTM) special publication 399 on the tan silty sandy fill soil materials at the above referenced site. Based on the observations and test data the tan silty sandy fill soils were adequately compacted at the tested locations.

Sincerely,

David Miller, PE

DEM/21DDM-0629E

DocuSigned by:

