

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

3/29/2023

SUBJECT: SFD2104-0030

SINGLE FAMILY DWELLING

To: Southeastern Construction

Here are the results of all Inspections located at 10 REMINGTON HILL DR:

Inspection Type: **ADDRESS**

Scheduled Date/Time: Completed Date/Time:

Inspector: **GIS Bucket**

Result: Remarks: Notes:

GAS PIPING Inspection Type:

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: **INSULATION**

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

SEWER CONNECTION Inspection Type:

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOOTING
Scheduled Date/Time: 9/27/2022
Completed Date/Time: 9/27/2022
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes: Wasn't ready

Inspection Type: FOOTING
Scheduled Date/Time: 9/29/2022
Completed Date/Time: 9/29/2022

Inspector: John B Kokoszka
Result: FAIL W/ PENALTY

Remarks:

Notes: The footing needs to cleaned out and bear solid

Inspection Type: FOOTING
Scheduled Date/Time: 10/5/2022
Completed Date/Time: 10/5/2022
Inspector: James T Hall
Result: APPROVED

Remarks: Notes:

Inspection Type: FOUNDATION Scheduled Date/Time: 11/2/2022 Completed Date/Time: 11/2/2022 Inspector: James T Hall Result: DISAPPROVED

Remarks:

Notes: Uncover all footings for foundation inspection

Inspection Type: FOUNDATION
Scheduled Date/Time: 11/10/2022
Completed Date/Time: 11/10/2022
Inspector: John B Kokoszka
Result: FAIL W/ PENALTY

Remarks:

Notes:

Piers where not footings uncovered. Bed joints need to meet code they appear to be bigger

than code allows Some of the foundation doesn't meet projection.



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION
Scheduled Date/Time: 1/9/2023
Completed Date/Time: 1/9/2023
Inspector: James T Hall
Result: FAIL W/ PENALTY

Remarks:

Notes: items from previous inspection not addressed

Inspection Type: FOUNDATION
Scheduled Date/Time: 1/12/2023
Completed Date/Time: 1/12/2023
Inspector: James T Hall
Result: APPROVED

Remarks:

Notes: Per engineer letter

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 1/18/2023
Completed Date/Time: 1/18/2023
Inspector: James T Hall
Result: APPROVED

Remarks: Notes:

Inspection Type: T-POLE
Scheduled Date/Time: 1/18/2023
Completed Date/Time: 1/18/2023
Inspector: James T Hall
Result: APPROVED

Remarks: Notes:





Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 3/13/2023
Completed Date/Time: 3/13/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes:

1.Nail lvl beam over garage door every 12" per documents2.Seal all cracks in air barriers on knee walls in garage3.Replace notched stud on back wall of garage for anchor bolt4.Missing mid story strapping on pipe in garage to left of door5.Missing air barrier under stairs in garage 6.Seal all holes in air barriers through out house7.Need compaction test on front and back porches before you pour8.No porch post installed at time of inspection9.Missing stud in foyer on closet wall10.Need repair letter for broken truss first one from left side and damaged gusset in front left bedroom over closet door11.Fire caulk wire at top plate in front left bathroom12.Nail jack stud at water cut off closest13.Nail 3 ply girder truss in master bedroom per truss documents from each side14.Solar heat gain and loss is over .30 on master bedroom and bathroom windows on end wall15.Need 2 king studs each end on windows in master bedroom and bathroom on end wall16.Master tub not in needs to be tested17.Missing baffles

in house18.Need 3' head of water on drain line test

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: 3/14/2023
Completed Date/Time: 3/14/2023
Inspector: CP Bucket
Result: APPROVED
Remarks: NOT NEEDED

Notes:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 3/29/2023 Completed Date/Time: 3/29/2023 Inspector: John B Kokoszka Result: DISAPPROVED

Remarks:

Notes:

Items 6 not completed Items 7,8 have not been completed yet

