



Reilly Road Industrial Park • P.O. Box 40408
Fayetteville, North Carolina 28309
(910) 864-TRUS • 1-800-868-5295
Fax (910) 864-4444 • www.comtechfay.com

ROOF & FLOOR TRUSSES HANGERS & BEAMS

October, 5 2021

To: Harnett County Building Inspections Department

Job: Weaver Devlp. - Lot 5 Barbecue Church Rd. / Harnett Co.

Concern: Floor Truss F2 Set Backwards

The double vertical web on the left side of the chase located at 4' 3" from the left end of the "F2" truss is only placed there in order to decrease the chase opening. Without the extra vertical web the chase would have a 2' 7" opening which surpasses the maximum chase opening of 2' 6". There are no additional loads added to the "F2" truss that requires the double vertical web to be there. The "F2" truss is essentially a symmetrical truss and can be turned so that the left end shown on the layout and truss drawing is on either the exterior wall or the stairway wall. Let me know if you need any further information.

No Repair is needed.

Sincerely, Dwayne Naylor

Dwayne Naylor

Design Manager

Cell 910-237-5045

email dnaylor@comtechfay.com

Comtech, Inc.