

DAVID MILLER, PE  
6300 Creedmoor Rd, STE 170#363  
Raleigh, NC 27612  
(919) 422-8932 (Office); DAVE@DMA-PA.COM

August 19, 2021

Weaver Development Company  
DBA: Weaver Homes  
309 Wagoner Drive  
Fayetteville, NC 28303  
Johnny 910-978-0435  
Brooke Weaver ; brooke@weaver-homes.com  
e-mailed to: johnny@weaver-homes.com ; Duston Blackwell 919-606-4696  
e-mailed to: cdb1971@gmail.com ;

RE: Engineering - Foundation Analysis  
Lot 1 Williams Farms Subdivision, Erwin NC  
Project No.: 21DDM-0819B

To whom it may concern:

The undersigned arrived on-site 8-19-21 to observe, probe and perform Dynamic Cone Penetrometer (DCP) testing in general accordance with the American Standard Testing Methods (ASTM) special publication 399 on the grey silty sandy fill soil materials at the above referenced site. Based on the observations and test data the grey silty sandy fill soils were adequately compacted at the tested locations.

Sincerely,

David Miller, PE

DEM/21DDM-0819B



2004 Josie Williams Rd.  
ERWIN, NC 28339