

DAVID MILLER, PE

6300 Creedmoor Rd, STE 170#363
Raleigh, NC 27612
(919) 422-8932 (Office); DAVE@DMA-PA.COM

August 19, 2021

Weaver Development Company
DBA: Weaver Homes
309 Wagoner Drive
Fayetteville, NC 28303
Johnny 910-978-0435
Brooke Weaver ; brooke@weaver-homes.com
e-mailed to: johnny@weaver-homes.com ; Duston Blackwell 919-606-4696
e-mailed to: cdb1971@gmail.com ;

RE: Engineering - Foundation Analysis
Lot 2 Williams Farms Subdivision, Erwin NC
Project No.: 21DDM-0819C

To whom it may concern:

The undersigned arrived on-site 8-19-21 to observe, probe and perform Dynamic Cone Penetrometer (DCP) testing in general accordance with the American Standard Testing Methods (ASTM) special publication 399 on the grey silty sandy fill soil materials at the above referenced site. Based on the observations and test data the grey silty sandy fill soils were adequately compacted at the tested locations.

Sincerely,

David Miller, PE

DEM/21DDM-0819C



1968 Josie Williams Rd
ERWIN. NC 28339