



Wise Engineering  
3915 Old Fairground Rd.  
Angier, NC 27501  
(919)894-2203

February 14, 2022

Gene's Backhoe Service  
Tyler Nordan  
1340 Two Claude Rd  
Willow Spring, NC 27592

Subject: 649 Fred Burns Rd, Holly Springs, NC 27540

Mr. Nordan,

A representative from Wise Engineering (WE) was on-site to observe the existing footing excavations at 649 Fred Burns Rd, Holly Springs, NC 27540 due to excessive moisture in the footings.

Based on our observations and the results of our field tests, the standing water within the footing excavations should be removed the mud in the bottom of the footings should be "mucked out". Provided the standing water is removed and the footing is adequately "mucked out" then the soil within the footing excavations is structurally adequate to support the anticipated loading conditions.

If you need additional information or have other questions, please let us know.

Sincerely,

Taylor Poulos

Randy K. Wise, PE

