

A A TAKLA ENGINEERING, PLLC Consulting. Design. Efficiency.

Atef A. Takla, PE | 919-358-1758 | ateftakla@taklaengr.com

	A C A TIPE
IC Firm License No. P-1446 18 Vivaldi Dr. Durham, NC 27712	BURNETH CAROLINATION OF ESSION OF THE PROPERTY
Project: Location: Date: Company: Care Of: Lot# 4 Purfor place FNONAY-Vanna NC 210 22 Luis Lopex	14578 NGINEER AZIZ TAKAMANANANANANANANANANANANANANANANANANAN
AS FEQUESTED A. Takla	Visited the SHE
and observed the P	ooting Trenches
of the House and for	und adequate
per plan, met HCRC	- 2018
0. K 10 place \$ 57 5	tone for
Deep Trenches.	V
0.K 10 Pour	
	- Company of the Comp

Limitations of Inspection: Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, shoring, means and methods of construction are considered beyond the scope of this report.



A A TAKLA ENGINEERING, PLLC Consulting. Design. Efficiency.

Atef A. Takla, PE | 919-358-1758 | ateftakla@taklaengr.com

NC Firm License No. P-1446 418 Vivaldi Dr. Durham, NC 27712	
Project: Location: Date: Company: Care Of: Lot# 41 Purfoy Place Fuquay-varina Ja578 Luis Lopez SEAL JA578 AZIZ TAKARAMANA AZIZ TAKARAMANA SEAL JA578 JA578 JA578 JA578 JA578 JA778 JA77	
AS PEQUESTED A. Takla prepared This	
7 projection repairs and found	
adequate. In-place Dowiels and	
Additional footing Are adequate	
O.K. 10 Pour	

Limitations of Inspection: Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, shoring, means and methods of construction are considered beyond the scope of this report.