

Feb. 11, 2025

North Carolina Custom Motors

After the inspection at 190 Round Rock Ln. Broadway, NC.

I have found two items that need corrections, the first one is a leak, and the second one is the ridge vent. After the inspections there are no other repairs.

Sincerely,

644 Heather Glenn Place Asheboro, NC 27205

336-308-4312 Office 336-215-0520 Greensboro 704-500-2072 Charlotte dstone1014@yahoo.com