




System: 
 Repair: 

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.

System: Gravity to Serial Dist.
 Lines: 1-4, (435')
 Accepted Status System
 0.35 Soil LTAR
 18" Trench Bottom

Repair: Gravity to Serial Dist.
 Lines: 5-8, (365')
 Accepted Status System
 0.35 Soil LTAR
 18" Trench Bottom



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
 Lot 78, Birchwood Subdivision
 Harnett County, North Carolina

Job# : 3753
 Drawn By : LW
 Date : 07/02/2021
 Revision: