


System: ———
 Repair: - - - -

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.

System: Gravity to Serial Dist.
 Lines: 1–3, (335')
 EZ Flow
 0.4 Soil LTAR
 18" Trench Bottom

Repair: Gravity to Serial Dist.
 Lines: 4–7, (373')
 EZ Flow
 0.4 Soil LTAR
 18" Trench Bottom



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
 Lot 2, Birchwood Subdivision
 Wake County, North Carolina

| |
|-------------------|
| Job# : 3753 |
| Drawn By : LW |
| Date : 08/17/2021 |
| Revision: |
| |
| |