I, MICHAEL P. GRIFFIN , certify that under my direction and supervision this map was drawn from an actual field survey, that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates. MAP 2007 PG 699 HARNETT CO. REGISTRY Witness my hand and seal this day of MONTH 2022. N/F WILLIAM CORDER DB 1542 PG 240 PC F SL 611-D 130.12 N 03°08'39" W 109 N 88°34'14" W 0.89 AC. 415 5 04°47'36" W SETBACKS CI FRONT 35' REAR 25' SIDE 10 GEORGIE DRIVE CORNER SIDE 20' REVISION: 19' BACK 5/16/22 60' PUBLIC R/W REVISION: 8' RIGHT 4/12/22 CI R=280.00' L=84.52' N03°44'41"W 84.20' LEGEND PRELIMINARY EXISTING IRON PIPE FLARED END SECTION WATER METER IRON PIPE SET WM

RIGHT OF WAY

NOW OR FORMERLY

CO

CLEAN OUT

FIRE HYDRANT

NOT FOR RECORDATION,