MICHAEL P. GRIFFIN , certify that under my direction and supervision this map was drawn from an actual field survey, that the error of closure of the survey as calculated by coordinates is 1: 10,000+; that the area shown hereon was calculated by coordinates. MAP 2007 PG 699 HARNETT CO. REGISTRY Witness my hand and seal this day of MONTH 2022. WILLIAM CORDER DB 1542 PG 240 PC F SL 611-D 130.12 N 03°08'39" W -0.89 AC. PROPOSED DWELLING 12°38'08" SETBACKS 5 04°47'36" W CI FRONT REAR 35 25' 10' SIDE GEORGIE DRIVE CORNER SIDE 20' 60' PUBLIC R/W REVISION: 8' RIGHT 4/12/22 CI R=280.00' L=84.52' NO3°44'41"W 84.20' LEGEND FLARED END SECTION PRELIMINARY EXISTING IRON PIPE IRON PIPE SET WATER METER WM

R/W

N/F

RIGHT OF WAY

NOW OR FORMERLY

CLEAN OUT

FIRE HYDRANT

CO

NOT FOR RECORDATION,