



System: HHHHHH Repair: -----

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.



System: Pressure Manifold Lines: 3-5 (230') Accepted Status System 0.4 Soil LTAR 12" Trench Bottom At Grade

Repair: Pressure Manifold Lines: 1, 2 (245') T&J Panel Block 0.4 Soil LTAR 14" Trench Bottom At Grade





Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout 90gal/day/br Engineered Flow Reduction Lot 75, Birchwood Subdivision Harnett County, North Carolina Job# : 3753

Drawn By : MB

Date : 05/02/2021

Revision: