

# AA TAKLA ENGINEERING, PLLC

Consulting. Design. Efficiency.

Atef A. Takla, PE | 919-358-1758 | ateftakla@taklaengr.com


NC Firm License No. P-1446  
418 Vivaldi Dr. Durham, NC 27712

Project: LOT #107  
1203 Keith Hills dr  
Location: Lillington, NC  
Date: 6/21/22  
Company: \_\_\_\_\_  
Care Of: Nelson



As requested, A. Takla visited the site and observed the foundation of the Home and found adequate, meet NCP-C-2018  
Rear porch walls (as-constructed) are adequate (BACK Fill w/ #1 57 stone)

Limitations of Inspection: Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, shoring, means and methods of construction are considered beyond the scope of this report.




# AA TAKLA ENGINEERING, PLLC

Consulting. Design. Efficiency.

Atef A. Takla, PE | 919-358-1758 | ateftakla@taklaengr.com

NC Firm License No. P-1446  
418 Vivaldi Dr. Durham, NC 27712

Project: (LOT# 107)  
Location: 1203 Keith hills dr  
Date: Lillington,  
6/3/22  
Company: \_\_\_\_\_  
Care Of: Nelson Jose  
(919)427-8314



AS REQUESTED, A. TAKLA VISITED THE property  
and observed THE Footing Trenches  
of THE proposed House and found  
adequate pour Trenches Full Depth  
with concrete to rear Trenches  
per plan & meet NCRC-2018  
O.K TO pour

Limitations of Inspection: Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, shoring, means and methods of construction are considered beyond the scope of this report.