



RE: Signature Home Builders / Lot 12 Williams Farms / F06 Floor Truss

To whom it may concern,

In designing the truss system for the subject project, it was observed by the designer that the head of the stairway would extend beyond the right end bearing for the F06 floor truss. Anticipating a future repair the end condition of the truss was designed with a “fire cut” to allow for the stair stringers to extend beyond the bearing and into the floor truss without necessitating a cut of the truss. Though the stairway is supported by the adjacent walls, it is anticipated and permissible for additional framing to be applied to the end of the truss at the transition with minimal load being applied to the truss. Since there is no observable damage to the truss, no repair is required and any additional framing attached to the truss is as deemed necessary by the builder to necessitate the proper transition from the stairway to the landing.

Please advise if additional information is required and feel free to contact me if there are any questions or concerns.

Regards,

Anthony Williams

Comtech Design