


System: Gravity to Serial Dist. Lines: 1—4, (345') Accepted Status System 0.35 Soil LTAR

Repair: Pressure Manifold Lines: 5-8, (305') T&J Panel 50% Reduction 0.35 Soil LTAR





Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout Lot 183, Birchwood Subdivision Harnett County, North Carolina Job#: 3753

Drawn By: LW

Date: 8/27/2022

Revision: