


SITE SKETCH

REVIS 2/27/23




System:
 Repair:

- *Keep tanks and drain lines 10' from property lines.
- *Not a survey.
- *Not a guarantee of a septic permit.
- *Keep supply lines >5' from property lines.
- *Some lines are flagged longer in the field than lengths indicate.
- *No grading septic area.

System: At-Grade Pressure Manifold
 Lines: 1-4 (201')
 T&J Panel 50% reduction
 0.3 Soil LTAR
 14" Trench Bottom

Repair: Drip Irrigation
 Area: 5965 Sq Ft
 TSII Drip
 0.15 Soil LTAR



Central Carolina Soil Consulting, PLLC
 1900 South Main Street, Suite 110
 Wake Forest, North Carolina 27587
 Phone (919)569-6704 Fax (919)569-6703

4-Bedroom Septic Layout
 w/engineered flow reduction
 Lot 184, Birchwood Subdivision
 Harnett County, North Carolina

Job# : 3753
Drawn By : MB
Date : 8/27/2022
Revision:01/19/2023