

Howerton Services, PLLC
License # P-1716
3513 Cathedral Bell Road
Raleigh, NC 27614
(919) 270-3460

December 1, 2022

Subject: 32 Lambert Lane
Fuquay Varina, NC 27526
Framing Inspection Letter
Harnett County Permit #: SFD2208-0054

Based on the request of the Contractor, I looked at 1 item from the framing inspection notice for code compliance. My assessment and recommendations are as follows:

- The double 2x10 beam above the stairs to the 2nd floor was reduced to a double 2x6 beam. The double 2x6 beam is sufficient to carry the load from above.

The double 2x6 beam as installed meets all the requirements of the 2018 North Carolina Building Code for Residences.



12 01 2022