



September 26, 2024

Kirby Johnson  
Johnson Farms  
12232 US-79 Bus. West  
Clayton, NC 27520  
Email: wrbarefoot@yahoo.com

Reference: Engineering Services  
Permit # SFD2209-0009  
891 Raynor Road  
Spring Lake, NC 28390  
TE&D Project No.: 2401-020836

As requested by the builder, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following items:

- 1) Footing projection repair specifications.


The following conclusions and recommendations were noted:

- 1) Based on our observations and analysis, the footing is to be repaired per the detail on page 3 of this report. Upon completion, the newly added sections of concrete will provide the required support for the anticipated loading conditions.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,  
Tyndall Engineering & Design

  
Tripp Amos  
KH | 2401-020836

  
Prentice Tyndall Jr., P.E.






### Site Inspected



### Affected Footings



F



### Footing Repair

