

This design is valid until 3/30/2024

Damaged Beams must not be used

Dry service conditions, unless noted otherwise
 LVL not to be treated with fire retardant or corrosive

Design assumes top edge is laterally restrained
Provide lateral support at bearing points to avoid
lateral displacement and rotation

(800) 622-5850 www.metsawood.com/us

ICC-ES: ESR-3633

COMTECH



Address:


Harnett County, NC

Job Name: Ringled Residence/The Wildwood

Project #: J0922-4832

1.750" X 11.875" Kerto-S LVL 2-Ply - PASSED FB<sub>1</sub>

Level: Level



| Member Information |               |                |              |     | Reactions UNPATTERNED lb (Uplift) |      |      |              |       |          |           |  |  |
|--------------------|---------------|----------------|--------------|-----|-----------------------------------|------|------|--------------|-------|----------|-----------|--|--|
| Туре:              | Girder        | Application:   | Floor        | Brg | Direction                         | Live | •    | Dead         | Snow  | Wind     | Const     |  |  |
| Plies:             | 2             | Design Method: | ASD          | 1   | Vertical                          | (    | )    | 829          | 773   | 0        | 0         |  |  |
| Moisture Condition | : Dry         | Building Code: | IBC/IRC 2015 | 2   | Vertical                          | (    | )    | 829          | 773   | 0        | 0         |  |  |
| Deflection LL:     | 480           | Load Sharing:  | No           |     |                                   |      |      |              |       |          |           |  |  |
| Deflection TL:     | 240           | Deck:          | Not Checked  |     |                                   |      |      |              |       |          |           |  |  |
| Importance:        | Normal - II   |                |              |     |                                   |      |      |              |       |          |           |  |  |
| Temperature:       | Temp <= 100°F |                |              | -   |                                   |      |      |              |       |          |           |  |  |
|                    |               |                |              | Bea | rings                             |      |      |              |       |          |           |  |  |
|                    |               |                |              | Bea | aring Length                      | Dir. | Сар. | React D/L lb | Total | Ld. Case | Ld. Comb. |  |  |
|                    |               |                |              | 1 - | SPF 3.500"                        | Vert | 31%  | 829 / 773    | 1602  | L        | D+S       |  |  |
| Amalysis Basyli    |               |                |              | 2 - | SPF 3.500"                        | Vert | 31%  | 829 / 773    | 1602  | L        | D+S       |  |  |

### Analysis Results

| ĺ | Analysis     | Actual         | Location  | Allowed       | Capacity    | Comb. | Case |
|---|--------------|----------------|-----------|---------------|-------------|-------|------|
|   | Moment       | 4481 ft-lb     | 6' 1/2"   | 22897 ft-lb   | 0.196 (20%) | D+S   | L    |
|   | Unbraced     | 4481 ft-lb     | 6' 1/2"   | 8283 ft-lb    | 0.541 (54%) | D+S   | L    |
|   | Shear        | 1272 lb        | 10'9 5/8" | 10197 lb      | 0.125 (12%) | D+S   | L    |
|   | LL Defl inch | 0.060 (L/2331) | 6' 1/2"   | 0.291 (L/480) | 0.206 (21%) | S     | L    |
|   | TL Defl inch | 0.124 (L/1125) | 6' 1/2"   | 0.581 (L/240) | 0.213 (21%) | D+S   | L    |

## **Design Notes**

- 1 Provide support to prevent lateral movement and rotation at the end bearings. Lateral support may also be required at the interior bearings by the building code.
- 2 Girders are designed to be supported on the bottom edge only.
- 3 Multiple plies must be fastened together as per manufacturer's details.
- 4 Top loads must be supported equally by all plies.
- 5 Top must be laterally braced at end bearings.
- 6 Bottom must be laterally braced at end bearings.
- 7 Lateral slenderness ratio based on single ply width.

| . Later at civil active of talle bacoa off chilgie pry maan. |             |          |            |      |          |        |           |          |             |          |  |
|--|-------------|----------|------------|------|----------|--------|-----------|----------|-------------|----------|--|
| ID   | Load Type   | Location | Trib Width | Side | Dead 0.9 | Live 1 | Snow 1.15 | Wind 1.6 | Const. 1.25 | Comments |  |
| 1  | Uniform     |          |            | Тор  | 128 PLF  | 0 PLF  | 128 PLF   | 0 PLF    | 0 PLF       | A04      |  |
|  | Self Weight |          |            |      | 9 PLF    |        |           |          |             |          |  |

NOtes
Calculated Structured Designs is responsible only of the structural adequacy of this component based on the design criteria and loadings shown. It is the responsibility of the customer and/or the contractor to ensure the component suitability of the intended application, and to verify the dimensions and loads.

Dry service conditions, unless noted otherwise
 LVL not to be treated with fire retardant or corrosive

# Handling & Installation

L. UV. beams must not be cut or drilled
 Refer to manufacturer's product information regarding installation requirements, multi-ply fastening details, beam strength values, and code approvals
 Damaged Beams must not be used

- Design assumes top edge is laterally restrained
  Provide lateral support at bearing points to avoid
  lateral displacement and rotation

Metsä Wood 301 Merritt 7 Building, 2nd Floor Norwalk, CT 06851 (800) 622-5850 www.metsawood.com/us ICC-ES: ESR-3633

Manufacturer Info

Comtech, Inc. 1001 S. Reilly Road, Suite #639 Fayetteville, NC USA 28314 910-864-TRUS



This design is valid until 3/30/2024

For flat roofs provide proper drainage to prevent ponding