## HAL OWEN & ASSOCIATES, INC.

## SOIL & ENVIRONMENTAL SCIENTISTS

P.O. Box 400, Lillington NC 27546-0400 Phone (910) 893-8743 / Fax (910) 893-3594 www.halowensoil.com

22 September 2023

Paul Lyon Lyon Builders 2139 Barbecue Church Road Sanford, NC 27332-1414

Reference: Soil Investigation and Septic System Design

4071 Barbecue Church Road; PIN 9578-18-2948.000

Lot #2 Lyon Builders Inc Map#2022-545

Dear Mr. Lyon,

A site investigation was conducted on 6 July 2023 for the above referenced property, which is located on the western side of Barbecue Church Road (SR 1209) in the Barbecue Township in Harnett County, North Carolina. The purpose of the investigation was to determine the ability of this lot to support a subsurface sewage waste disposal system and 100% repair area for a typical three-bedroom home. Public water supplies will be utilized for this lot.

All ratings and determinations were made in accordance with "Laws and Rules for Sewage Treatment and Disposal Systems, 15A NCAC 18A .1900". This report represents my professional opinion but does not guarantee or represent permit approval for any lot by the Local Health Department. The permit you receive from the Local Health Department may contain some modifications or amendments to our submitted design. Please carefully review your permit and adhere to all prescribed requirements.

## **SEPTIC SYSTEM DESIGN**

The proposed single family residential home will contain three bedrooms and generate a design flow of 360 gallons per day (Figure 2). A 1000 gallon (minimum) septic tank is required with an approved effluent filter. The addition of a 1000-gallon pump tank will be necessary to pump effluent uphill to the proposed drainfield.

The initial septic system is proposed as a pump driven system to 300 linear feet of Infiltrator Quick4 Plus standard chamber drainlines utilizing a 25% reduction in total drainline length (Figure 2). A long-term application rate (LTAR) of 0.3 gal/day/ft² was used to design the drainfield. A pressure manifold will be used to deliver effluent in parallel distribution to five 60-ft long drainlines. The drainlines shall be installed on contour with maximum trench bottom depths at 15 inches below surface.

The repair septic system is proposed as a pump driven system to 134 linear feet of Horizontal Permeable Panel Block drainlines utilizing a 50% reduction in total drainline length (Figure 2). A long-term application rate (LTAR) of 0.45 gal/day/ft<sup>2</sup> was used to design the drainfield. A pressure manifold will be used to deliver effluent in serial distribution to two unequal length drainlines, connected by overflow pipes. The drainlines shall be installed on contour with maximum trench bottom depths at 15 inches below surface.

All regulatory setbacks for a septic system shall be maintained. Drainlines must be installed at least 9 feet apart on center. The septic system (including tanks) must be at least 10 feet from a property line, 5 feet from a home, 50 feet from a surface water, and 100 feet from an individual well (50ft for repair systems).

Potential septic system drainlines have been demonstrated with various colored pin flags that are located on the lot. It is important to protect the areas designated for installation of the septic system or repair area from all land disturbing activities. It is recommended that a staked line or protective fence be placed around the system prior to construction to eliminate any potential damage to the soil or the layout of the system.

## **CONCLUSION**

This report and the attached septic system design information will need to be submitted to the Local Health Department for review and the permitting process. I appreciate the opportunity to provide this service and hope to be allowed to assist you again in the future. If you have any questions or need additional information, please contact me at your convenience.

Sincerely,

Britt Wilson

Licensed Soil Scientist

WW Welso

Hal Owen

Licensed Soil Scientist

