

Date: 09/01/2023

To: **Joseph Davis**
Caruso Homes
206 High House Road
Cary, NC 27512
jdavis@carusohomes.com
240-539-6282

Re: **Framing Issue**
Location: 1425 Baptist Grove Rd. (Fuquay-Varina, NC)
JDS Project No.: RDU2307952
Date of Inspection: 9/1/23

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

Observations


The client has requested evaluation of the steel I beam bearing on both the jack stud columns and the headers at both the front and rear bearing end instead of bearing solely on the jack stud columns as specified in the plans.

Recommendations

Based on our onsite observation and review the current bearing conditions are adequate for the calculated loads at both the noted bearing locations. No further action is required.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 980-240-5681.

Respectfully Submitted,
Zachary Lower



Reviewing Engineer: Uchenna Onwuemene, PE

