

ECS Southeast, LLP

6151 Raeford Road, Suite A Fayetteville, NC 28304 9104013288 9103230539

LETTER OF TRANSMITTAL

May 12, 2023

Precision Custom Homes

Permits:

RE:

Raeford, NC 28376

ATTN: Shaun Gardner

Location: 303 Solomon

ECS Job # 33:6442-B

Cameron, NC 28326

Liberty Meadows Lot 43

Field Reports

X For your use X

As requested

CC:

Precision Custom Homes - Allen Peterson

& Rouset

Precision Custom Homes - Lauren Ceruti

ENCL:

Field Report # 1

5/11/2023

Jack Cowsert, P.E.

Office Manager

Aaron Kyle Adair Team Leader

Disclaimer

^{1.} This report (and any attachments) shall not be reproduced except in full without prior written approval of ECS.

^{2.} The information in this report relates only to the activities performed on the report date.

^{3.} Where appropriate, this report includes statements as to compliance with applicable project drawings, and specifications for the activities, performed on this report date.

^{4.} Incomplete or non-conforming work will be reported for future resolution.

^{5.} The results of samples and/or specimens obtained or prepared for subsequent laboratory testing will be presented in separate reports/documents.



ECS Southeast, LLP 6151 Raeford Road, Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project Liberty Meadows Lot 43

Location Cameron, NC

Client Precision Custom Homes

Contractor Precision Custom Homes

FIELD REPORT

Project No. **33:6442-B**

Report No. 1

Day & Date Thursday 5/11/2023

Weather 70 °/ Sunny

On-Site Time 2.00

Lab Time 0.00

Travel Time* 0.00

Total 2.00

Re Obs Time 0.00

Remarks

Trip Charges* Tolls/Parking* Mileage* Time of Arrival Departure
Chargeable Items 3:30P 5:30P


* Travel time and mileage will be billed in accordance with the contract.

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

ECS arrived on site, as requested, to check the bearing capacity of soils via hand auger/DCP method for monolithic foundation. Footings were not excavated. Please see the attached sketch and data sheet for details.

A total of 4 hand auger/DCP evaluations were performed to a depth of approximately 3 feet below the current footing sub grade elevation. Test results indicated that the materials in place (at the locations and elevations tested) did appear to be suitable to support the design bearing capacity 2,000 psf.

ECS will return, as requested, for additional services.



Harvey Sangster 5/11/2023
Liberty Meadows lot43
Poj # 6442-B
W/O # 72177

KEY



DCP test Location

Transmittal Page 3/4



NC Registered Firm # F-1078



Report of Spread Footing - Foundation Observations

Project:	Liberty Meadows Lot 43	Project No.:	33:6442-B
Location:	303 Solomon	Day/Date:	5/11/2023

Contractor: Cameron - Moore - NC - 28326

Contractor: Precision Custom Homes

Footing Number	Location	Size (W x H x L)		Footing Bottom Elevation			December of	Required Blow Counts	Danima
		Design	Actual	Design **	Depth of Undercut (in)	Description of Steel Placed	Description of Subgrade Material	# of Blows / Increment	Design Bearing Pressure
1	Southeast corner of foundation footing	хх	хх	N/A	N/A		(0)Orange SAND(-1/-3) Grey SAND	6	2000
								(0)7,17,20(-1)18,18,18(- 2)15,17,18(-3)12,17,16	
2	Southwest corner of foundation footing	x x	хх	N/A	N/A			6 (0)10,10,12(-1)15,17,15 (-2)18,17,18(-3) 15,16,17	2000
3	Northwest corner of foundation footing	хх	хх	N/A	N/A		(0)Orange SAND(-1)Grey SAND(-2/-3)Tan SAND	6 (0)9,7,6(-1)12,10,11(-2) 17,17,17(-3)16,13,17	2000
4	Northeast corner of foundation footing	хх	хх	N/A	N/A		(0/-1)Orange SAND(-2)Grey SAND(-3)Tan SAND	6 (0)15,16,17(-1)15,17,15 (-2)18,18,17(-3) 16,13,13	2000

** SGE: Subgrade Elevation to be determined by surveyor.	Ву:	Harvey Lamar Sangster	
		ECS Southeast, LLP	

WO: 72177