







UFP Mid Atlantic LLC, 5631 S. NC 62, Burlington, NC, Micah Clayton

Run: 8.62 S Sep 22 2022 Print: 8.620 S Sep 22 2022 MiTek Industries, Inc. Fri Apr 21 15:25:06 Page: 1




component is responsibility of the Building Designer. Building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.



















UFP Mid Atlantic LLC, 5631 S. NC 62, Burlington, NC, Micah Clayton


Run: 8.62 S Sep 22 2022 Print: 8.620 S Sep 22 2022 MiTek Industries, Inc. Fri Apr 21 15:25:08

Page: 1  $ID: HZbTmoeUwPldT\_OH0roBaPyibU6-5ouOUymTp22rrRftTtvItotSzGN9exo3Pf?BkazOTJffinality to the test of test$ 




governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute
















































Job	Truss		Truss Type		Qty	Ply	PBS\SELMA	TRADITION	IAL GR ROOF			
72314550	DCJ		Truss	4	1	lob Reference (options!)						
	P Mid Atlantic LLC, 5631 S. NC 62, Burlington, NC, Micah C					Job Reference (optional) Sep 22 2022 MiTek Industries, Inc. Fri Apr 21 15:25:10 Page						
					-					Dzqo44t6tTMtzUIoTzOTJd		
				-0-10-8 0-10-8	<u>, 2-1-7</u> 2-1-7							
			0-5-15		3 <sup>12</sup> 3 <sup>-</sup> B1 3x4=		4-0-1	-				
Loading TCLL (roof)	(psf) 20.0	Spacing Plate Grip DOL	2-0-0 1.15	CSI TC		FL t(LL)	in (loc) 0.00 4-7	l/defl L/d >999 240	MT20	<b>GRIP</b> 244/190		
TCDL BCLL	10.0 0.0*	Lumber DOL Rep Stress Incr	1.15 YES	BC WB		t(CT) rz(CT)	0.00 7 n/a -	>999 180 n/a n/a	1			
BCDL	10.0	Code	IRC2015/TPI2014	Matrix-MP					Weight: 8 lb	FT = 20%		
LUMBER TOP CHORD BOT CHORD REACTIONS	2x4 SP No.2 BOT CHORD					Structural wood sheathing directly applied or 2-1-7 oc purlins. Rigid ceiling directly applied or 10-0-0 oc bracing.						
	Max Horiz 2 Max Uplift 2	Mechanical, (min. 0-1-{ 2=33 (LC 6) 2=-76 (LC 6), 3=-25 (L0 2=146 (LC 1), 3=48 (L0	8) C 6), 4=-9 (LC 6)	-,,								
<ul> <li>exterior zor forces &amp; M</li> <li>This truss h</li> <li>* This truss the bottom</li> <li>Provide me joint 4.</li> </ul>	CE 7-10; Vult=130mph ( ne and C-C Exterior (2) WFRS for reactions sh has been designed for s has been designed for chord and any other m echanical connection (b	(3-second gust) Vasd= ) zone; cantilever left a own; Lumber DOL=1.6 a 10.0 psf bottom chor r a live load of 20.0psf nembers. by others) of truss to be	All forces 250 (ib) or less exc 103mph; TCDL=6.0psf; BCDL and right exposed ; end vertica 60 plate grip DOL=1.60 rd live load nonconcurrent with f on the bottom chord in all are earing plate capable of withsta rnational Residential Code sed	_=6.0psf; h=35ft; Cat. Il left and right expose n any other live loads. eas where a rectangle anding 25 lb uplift at jo	ed; porch left ex 3-06-00 tall by pint 3, 76 lb upli	xposed;C-C fi 2-00-00 wid	or members and e will fit between nd 9 lb uplift at					
								Manne	JORTH C	AROLINA PAL PRESIET		











component is responsibility of the Building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the operific building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the operific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a UFPI plant. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Safety Information (BCSI) for general guidance regarding storage, erection and bracing available from SBCA and Truss Plate Institute.














































Job	Truss	Truss Type		Qty	Ply	PBS\SELM	A TRADI	TION	AL GR ROOF		
72314550	V6	Truss	1		Job Refere	Job Reference (optional)					
JFP Mid Atlantic LLC, 5631 S. NO	C 62, Burlington, NC, Micah	Clayton	Run: 8.62	S Sep 22 2	022 Print: 8.620			,	Inc. Fri Apr 21 15	:25:12	Page: 1
					ID:clpyjolA2	ZC42tTJ_MmJxM	ye3c2a	BuJJpzt	GYHK2yeij_E2e2	9_umtanzfKHz0	OtMzOTJb
				<u>1-6-</u> 1-6-	X	3-0-11 2 2 0-4-10					
		<u>  1-2-0</u>   <u>0-10-5</u>	4 4	9 <sup>12</sup> 1 3x4	3x4= 2 B1 81 3	3 ₩4 ₩					
				/	3-0-11						
Plate Offsets (X, Y): [2:0-	-2-0,Edge]			I		1					
TCLL (roof) TCDL BCLL	(psf)Spacing20.0Plate Grip DOL10.0Lumber DOL0.0*Rep Stress Incr10.0Code	2-0-0 1.15 1.15 1.15 YES IRC2015/TPI2014	CSI TC BC WB Matrix-MP	0.07 0.06 0.00	DEFL Vert(LL) Vert(TL) Horiz(TL)	in (loc) n/a - n/a - 0.00 3	l/defl n/a n/a n/a	L/d 999 999 n/a	PLATES MT20 Weight: 9 lb	<b>GRIP</b> 244/190 FT = 20%	
LUMBER TOP CHORD 2x4 SP No.2 BOT CHORD 2x4 SP No.2 REACTIONS (Ib/size Max Hi	,	0-1-8), 3=122/3-0-11, (min. 0-1-	8)	BRACING TOP CHOI BOT CHOI		Structural wood s Rigid ceiling direc			applied or 3-1-5 c 0-0 oc bracing.	c purlins.	
FORCES       (         NOTES       1)       Unbalanced roof live loads         2)       Wind: ASCE 7-10; Vult=13 exterior zone and C-C Ext for reactions shown; Lumb         3)       Gable requires continuous         4)       This truss has been design         5)       * This truss has been design the bottom chord and any         6)       Provide mechanical conne	s have been considered for 30mph (3-second gust) Vasi erior (2) zone; cantilever lef er DOL=1.60 plate grip DO s bottom chord bearing. ned for a 10.0 psf bottom ch gned for a live load of 20.0p other members. ection (by others) of truss to	<ul> <li>All forces 250 (lb) or less exc</li> <li>this design.</li> <li>103mph; TCDL=6.0psf; BCDI</li> <li>and right exposed ; end vertica</li> </ul>	=6.0psf; h=35ft; Ca I left and right expo n any other live load as where a rectang anding 16 lb uplift at	sed;C-Ċ for ls. le 3-06-00 ta	members and f all by 2-00-00 w 16 lb uplift at joi	orces & MWFRS ride will fit betwee	Q	and the second s	NORTH C SE 025	AROLIN SIONAL 9461/23 NEER	A MARINE MARINE



