



| Products |        |   |       |         |
|----------|--------|---|-------|---------|
| PlotID   | Length | Product                                 | Plies | Net Qty |
| BM-1     | 24-0-0 | 1-3/4" x 9-1/2" VERSA-LAM® 2.0 3100 SP  | 2     | 2       |
| BM-2     | 10-0-0 | 1-3/4" x 9-1/2" VERSA-LAM® 2.0 3100 SP  | 2     | 2       |
| BM-3     | 8-0-0  | 1-3/4" x 9-1/2" VERSA-LAM® 2.0 3100 SP  | 2     | 2       |
| BM-4     | 22-0-0 | 1-3/4" x 11-7/8" VERSA-LAM® 2.0 3100 SP | 2     | 2       |

| Truss Connector Total List |         |     |
|----------------------------|---------|-----|
| Manuf                      | Product | Qty |
|                            | HTU26   | 7   |
|                            | LUS24   | 9   |

**WARNING!** Long span trusses, 60' or greater in length, require extreme care and experience for proper and safe handling and installation. For general handling and installation guidance, see the "Guide to Good Practice for Handling, Installing, Restraining & Bracing of Metal Plate Connected Wood Trusses ("BCSI"), JOINTLY PRODUCED BY SBCA and TPI. For project specific guidance, consult with a registered design professional. ATLANTIC assumes no responsibility for the handling, installation or bracing of trusses.

▲ = LEFT END OF TRUSS

REVISIONS:



Moncks Corner/Easley, SC (800) 475-3999  
Sparta, NC (336) 372-2226

**NOT FOR CONSTRUCTION**

Client: **MATTAMY HOMES-RALEIGH**  
 Job: **LOT 40 PROVIDENCE CREEK**  
 Plan Information:  
**GLADES-FH**

ROOF

NOT TO SCALE  
 Date: 07/07/23  
 Drawn By: BPT  
 Sales Rep: KYLE GIBSON  
 Job #: 23-4838-R01  
 Phone: