

Joe E Godwin Sr. , P.E., P.L.S.

Jason E Godwin , P.L.S.



1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: CARROLL CONST	DATE: 1.28.24
PROJECT: SHILOH S/D	CONTRACTOR: D. PEEBLES
ADDRESS: 60 HOLLY GROVE LN	TECHNICIAN: BH
LOT #: 6	

#### TEST SUMMARY

PERFORMED VERIFICATION OF FOOTING PROJECTION REPAIR AT SITE NOTED ABOVE.  
FOOTING REPAIR OK PER ENOCH ENGINEERS P.A. DESIGN.

#### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

#### RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.

Joe E Godwin Sr., P.E., P.L.S.

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

Jason E Godwin, P.L.S.



[www.enochengineers.com](http://www.enochengineers.com)

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT: CARROLL CONST	DATE: 1.28.24
PROJECT: SHILOH S/D	CONTRACTOR: D. PEEBLES
ADDRESS: 50 HOLLY GROVE LN	TECHNICIAN: BH
LOT #: 7	

#### TEST SUMMARY

PERFORMED VERIFICATION OF FOOTING PROJECTION REPAIR AT SITE NOTED ABOVE.  
FOOTING REPAIR OK PER ENOCH ENGINEERS P.A. DESIGN.

#### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

#### RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.