

Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

5/24/2024

SUBJECT: **SFD2309-0088**

SINGLE FAMILY DWELLING

To: THOMAS CLIFFORD STEVE JR

Here are the results of all Inspections located at 12583 MCDOUGALD RD:

Inspection Type: GAS PIPING

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FINAL SFD STEMWALL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 2/13/2024
Completed Date/Time: 2/14/2024
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 12583 MCDOUGALD RD BROADWAY 27505.

10/2/2023 11:30:45 AM

Inspection Type: FOOTING
Scheduled Date/Time: 2/14/2024
Completed Date/Time: 2/14/2024
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 2/22/2024
Completed Date/Time: 2/22/2024
Inspector: Steven Gazlay
Result: APPROVED

Remarks: Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time: 2/22/2024
Completed Date/Time: 2/22/2024
Inspector: Steven Gazlay
Result: DISAPPROVED

Remarks:

Notes: Missing R-10 insulation. Remove organic debris and broken block from fill areas. Need address

numbers posted onsite.

Inspection Type: FOUNDATION
Scheduled Date/Time: 2/26/2024
Completed Date/Time: 2/26/2024
Inspector: John B Kokoszka

Inspector: John B Kokoszka Result: APPROVED

Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: 3/8/2024 Completed Date/Time: 3/8/2024

Inspector: John B Kokoszka Result: DISAPPROVED

Remarks:

Notes: Missing sleeves at lug footing

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: 3/12/2024 Completed Date/Time: 3/12/2024 Inspector: John B Kokoszka Result: APPROVED

Remarks: Notes:

3 of 5



Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 3/12/2024 Completed Date/Time: 3/12/2024 Inspector: John B Kokoszka Result: **APPROVED**

Remarks: Notes:

Inspection Type: **SLAB** Scheduled Date/Time: 3/15/2024 Completed Date/Time: 3/15/2024 Inspector: John B Kokoszka Result: **APPROVED**

Remarks: Notes:

Inspection Type: **ROUGH IN** Scheduled Date/Time: 5/14/2024 Completed Date/Time: 5/14/2024 Inspector: James T Hall Result: **DISAPPROVED**

Remarks:

Notes:

No plans or truss docs in permit box and missing windows and doors

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 5/20/2024 Completed Date/Time: 5/20/2024 Inspector: James T Hall Result: **DISAPPROVED**

Remarks:

Notes: Missing windows and doors and missing correct flashing on windowsPorch post not installed at

> timeMissing nail guard at top plate on wire to left of panel in garageNail 2 & 3 ply trusses in throughout house per truss docsMissing nails in roof truss hangers in garageMissing air barriers

under knee walls in garageReplace short nails in hangers in garage near split of the

doorsMissing 3 nails at joists on ledgers in garage floor joistNeed 2 king studs on each side of lvl beam in back of garageMissing air barriers under stairs on back wallsNeed 3' head of water on

drain line test in laundry roomDouble studs at drain line in laundry room or use stud

guardsAnchor all interior load bearing walls per codeMissing hurricane straps on trusses at stairsMissing hurricane straps on 2 ply truss at bottom of stairs each endReplace all short nails in hangers for roof trusses with correct size nailsAnchor all toilet flanges per codeNeed 4 king

studs and 4 jack studs each end of back door stop inspection





Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 5/22/2024
Completed Date/Time: 5/22/2024
Inspector: Steven Gazlay
Result: CANCELLED

Remarks: Notes:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 5/23/2024
Completed Date/Time: 5/23/2024
Inspector: James T Hall
Result: FAIL W/ PENALTY

Remarks:

Notes: 1. Porch post not installed at time Of inspection

- 2. Nail all 2 & 3 ply trusses in throughout house
- 3. Missing 3 nails at joists on ledgers in garage floor joist
- 4. Missing air barriers under stairs on back walls
- 5. Need 3' head of water on drain line test in laundry room
- 6. Double studs at drain line in laundry room or use stud guards at sink
- 7. Fasten all toilet flanges per code
- 8. Missing smoke/ carbon detector outside master bedroom
- 9. Fire block top of chase in closet near master bedroom door
- 10. Missing anchor bolts in master bedroom hall and bedroom per code
- 11. Nail lvl header in master bedroom door every 12" and nail 2x10 header over triple window per code
- 12. Seal all holes in air Barriers in master bedroom over bathroom door
- 13. Replace all short nails in roof truss hangers in master bedroom and bathroom and front bedrooms with correct size nails throughout house including upstairs
- 14. Need two king studs on right side of master shower window
- 15. Missing nail guards on wires in master bathroom closet at top plate on end wall
- 16. Missing stud under top plate joint on back wall in master closet and strap top plate joints less than 24"
- 17. Need 3kind studs each end of opening in foyer
- 18. Fire caulk wires at top plate at spare bathroom door
- 19. Missing anchor bolts to left of window in corner in right front bedroom
- 20. Plans show 4-2x10 band for front porch
- 21. Window in stair landing is not tempered
- 22. Need 3 king studs each side of window in stairs
- 23. Seal all holes and air barriers upstairs
- 24. Rafters cannot be wider than ridge beam upstairs in roof framing
- 25. Need repair letter for cut trusses in stairway
- 26. Need 10 psi on gas line test
- 27. SFD2309-0088

