



FIELD REPORT

Project: Harrington Place Client: Smith douglas Date: 11/09/23
City: Broadway Forman: Ricky Contractor: A&R
Temperature: 60 Weather Conditions: Partly Cloudy Number of Trips: 1
Personnel: Hector Diaz Notified Ricky of A&R of results
1st Trip Arrived: 9:00 am Left: 10:00 am 2nd Trip Arrived: Left:

REMARKS

TME arrived on site as requested by contractor. Field tech spoke with Ricky and was informed contractor would be working on building pad 33. Field tech was informed building pad areas will only be needing approximately 4-5 inches of fill and William, be placing processed fill for material. Field tech decided to use a 1/2 inch steel probe rod due to lift being less than 6 inches and decided to probe areas. Field tech did find material probed firm and will return tomorrow for further testing and observations on other building pads.



Signature: [Handwritten signature]

TME's presence on site is to perform specific services limited to that scheduled by others based on the understanding of our agreement with our client. This report is not an acceptance or approval of site activities. Test results and inspections are representative of our observations only while onsite at that specific time and location and may vary at other locations. The frequency of testing is based on timely scheduling of work by others and properly conveying progress of work in progress. At no time will TME be responsible for Safety considerations for other parties on the site.