543 Pylon Dr Raleigh, NC 27606 (919) 480-1075 info@jdsconsulting.net

jdsconsulting.net

Date: 01/10/2024

To: Cody Ruhl

Drees Homes

7701 Six Forks Road Raleigh, NC 27615

cruhl@dreeshomes.com

919-222-1164

Re: Overhanging Sill Plate

Location: Lot 234 Serenity (24 Charming Ct. Fuquay-Varina, NC)

JDS Project No.: RDU2400248 Date of Inspection: 1/10/24

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

Observations

The client has requested evaluation of the right garage wall 2x4 sill plate overhanging between 0'' - 5/8'' across the entire span of the wall.

Recommendations

Based on our onsite observation and review the overhang observed is within allowable tolerances. No further action is required.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 980-240-5681.

Respectfully Submitted, Zachary Lower



Reviewing Engineer: Maxwell C. Danskin, PE