

LILLINGTON, NC 27546

Phone: Fax:

9/17/2025

SUBJECT: **SFD2401-0003**

SINGLE FAMILY DWELLING

To: LAMCO CUSTOM BUILDERS LLC

Here are the results of all Inspections located at 226 ROLLING PASTURE WAY:

Inspection Type: ADDRESS

Scheduled Date/Time: Completed Date/Time:

Inspector: GIS Bucket

Result: Remarks: Notes:

Inspection Type: GAS PIPING

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: CONDITIONAL POWER

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:





LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 1/15/2025
Completed Date/Time: 1/15/2025
Inspector: John B Kokoszka
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/14/2025 7:42 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: FOOTING
Scheduled Date/Time: 1/15/2025
Completed Date/Time: 1/15/2025

Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/14/2025 7:43 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: FOUNDATION
Scheduled Date/Time: 1/22/2025
Completed Date/Time: 1/22/2025
Inspector: John B Kokoszka

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/17/2025 8:33 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: 1/24/2025 Completed Date/Time: 1/24/2025 Inspector: Michelle Myatt Result: APPROVED

Remarks:

Notes:

1/24/2025 10:37 AM LAMCO CUSTOM BUILDERS LLC

foundation survey uploaded

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 2/3/2025 Completed Date/Time: 2/3/2025 Inspector: James T Hall Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/30/2025 3:06 PM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: 2/3/2025 Completed Date/Time: 2/3/2025 Inspector: James T Hall Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/30/2025 2:51 PM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: SLAB
Scheduled Date/Time: 2/7/2025
Completed Date/Time: 2/7/2025

Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 2/4/2025 4:46 PM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: ROUGH IN
Scheduled Date/Time: 3/5/2025
Completed Date/Time: 3/5/2025
Inspector: James T Hall
Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 3/3/2025 10:38 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Missing nails in roof truss hangers in master bedroomMissing insulation baffles on front wall in stairs and master closetFire caulk wires in master closet, spare bathroom and master bedroom

left of windowPorch post not installed at time of inspection

Inspection Type: INSULATION
Scheduled Date/Time: 3/10/2025
Completed Date/Time: 3/10/2025
Inspector: John B Kokoszka
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 3/6/2025 8:58 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com





LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 3/10/2025
Completed Date/Time: 3/10/2025
Inspector: John B Kokoszka
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 3/6/2025 8:57 AM LAMCO CUSTOM BUILDERS LLC

Contact Name: LAMCO CUSTOM BUILDERS LLC Site Address: 226 ROLLING PASTURE WAY

Phone: 9198594190

e-Mail: Lamcoacctdept@gmail.com

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 6/25/2025
Completed Date/Time: 6/25/2025
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes:

Water heater not boxed in. Need to label attic unit for max over current

Inspection Type: CONDITIONAL POWER

Scheduled Date/Time: 7/25/2025
Completed Date/Time: 7/25/2025
Inspector: John B Kokoszka
Result: APPROVED W/EXC

Remarks:

Notes: Need to label attic unit ok to check on final

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 8/6/2025 Completed Date/Time: 8/6/2025 Inspector: James Manhart

Result: APPROVED

Remarks:

Notes: needs pump final



Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL SFD STEMWALL**

Scheduled Date/Time: 8/13/2025
Completed Date/Time: 8/13/2025
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes:

LOCK BOX ON BACK DOOR 0525

1. Need to seal interior garage door2. Outlet in closet and garage needs to be GFCI3. Need to seal around clean out in kitchen pantry4. Need to seal around kitchen drain5. Attic light doesn't work 6. Need power to septic tank alarm7. Exterior of the house need 6 inches from grade from nontreated wood and need to make sure you have your slope away from the house 6 inches

within 10 feet

Inspection Type: FINAL SFD STEMWALL**

Scheduled Date/Time: 9/3/2025 Completed Date/Time: 9/3/2025

Inspector: Ricardo D Honrada Result: FAIL W/ PENALTY

Remarks:

Notes:

Front/left corner needs 6 inches below the bottom of vinyl siding then grading slope of 6 inches

per 10 feet.

Inspection Type: FINAL SFD STEMWALL**

Scheduled Date/Time: 9/10/2025 Completed Date/Time: 9/10/2025

Inspector: Ricardo D Honrada Result: FAIL W/ PENALTY

Remarks:

Notes:

LOCK BOX ON BACK DOOR 0525

Front and left side the corner ground needs to be sloped away from the house as per code. Still

not correct, the slopes graded towards to wall of the house.

Inspection Type: FINAL SFD STEMWALL**

Scheduled Date/Time: 9/16/2025 Completed Date/Time: 9/16/2025 Inspector: Deen Taylor Result: APPROVED

Remarks:

Notes: LOCK BOX ON BACK DOOR 0525

Drain installed